US EPA RECORDS CENTER REGION 5

ECOLOGY AND ENVIRONMENT, INC. FIELD INVESTIGATION TEAM SITE INSPECTION PLAN

A. GENERAL INFORMATION

SITE: NELSON BAOS, DRUM	TDD NO.: R5-8505-06
LOCATION: 1420 WIHUBBARD	U.S. EPA NO.: 120980680029
	SSID NO.:
CHICAGO.	WSTS NO.: 120082
PLAN PREPARED BY: KURT SIMS	DATE: 2-7-86
APPROVED BY:	DATE:
OBJECTIVE (including description of work to be performed INSPECTION, NO SETIME:	
DESIRED REPORT FORM: SI REPORT (2070-13)	HRS REPORT
OTHER (EXPLAIN)	
PROPOSED DATE OF INVESTIGATION: 3-18	-86
BACKGROUND REVIEW: Complete: Preliming	inary: V
HRS PRELIMINARY SCORE OF ROUTES: GW 2.26 SW	O AIR O
DIRECT CONTACT	FIRE AND EXPLOSION
TOTAL PRELIMINARY HRS SCORE VALUE (NO FIELD WORK)	<u>30</u>
PROJECTED HRS SCORE: GW 7, 26 SW	FIRE AND EXPLOSION
TOTAL PROJECTED HRS SCORE 1, 30	
IF NO SAMPLING, EXPLAIN ON PAGE 3.	
INSPECTION PRIORITY (BASED ON PROJECTED HRS SCORE): LO	N: HEDIUM: HIGH:
B. SITE/MASTE CHARACTERIS	STICS
WASTE TYPE(S): Liquid Solid	Sludge Ges
CHARACTERISTIC(S): Corrosive Ignitable	
Toxic Reactive Unknown Other (No	me)
	V EE-1 1/86

•	
. .	FACILITY DESCRIPTION: UNKNOWN
,	Principal Disposal Method (type and location): UNKNOWN
·	Unusual Features (dike integrity, power lines, terrain, etc.):
	Status: (active, inactive, unknown)
	History: (worker or non-worker injury; complaints from public; previous agency action): NELSON BROS. DRUM CO., WAS DESTROYED BY FIRE IN AUGUST 19RO. ARCHER WRECKING CO. WAS CONTRACTED TO COMPLETE DEMOLITIONA REMOVAL OF ~ 700 DR
	DRUMS REPORTED BY MSD TO BE 270 FULL OF APPARENT PAINT WASTE,
	C. HAZARD EVALUATION
	(Use Hazard Evaluation of Chemicals sheets for specific or representative chemicals present.): PRINT WASTES WERE STORED ON SITE PRIOR TO 1980 FIRE. PRESENT SITUATION UNKNOWN.

	MODIFICATIONS: UPGRADE TO LEVEL C IF HAU REGISTER
	1-5 PPM ABOUE BACKGROUND.
	SITE SAFETY PLAN ON FILE AT E & E: YES NO
·	D. FIELD WORK REQUIRED
	PERIMETER ESTABLISHMENT: MAP/SKETCH ATTACHED? YES NO
	Perimeter Identified? YES NO
	Zone(s) of Contamination Identified? YES NO
	Geophysical Work: YES NO
•	Type: Magnetometry Seismic Refraction GPR Resistivity Other
	Comments:
	Drilling: YES NO
	Well Location Identified: YES NO
	Drill Plan/Well Installation Plan Attached: YES NO
	Sampling Required: YES NO
	Type: GW SW Air Soil Waste Other
	Sampling Locations Identified: YES NO
	SUMMARY OF SAMPLING PROCEDURES: (Special Equipment, Facilities, or Procedures) NO SAMPLING DUE TO CLEANOR
	ACTIVITY IN 1980 SUPERVISED BY I.E.P.A.
	D.L.P.C.

E. ANALYTICAL SERVICES REQUIRED

RAS	SAS	CRL
REQUIRED: YES		
IF ND, EXPLAIN:	NOT NEED	ED
	G. SI NORK TEAM S	IZE/LIMITATION
TEAN MEMBER	DISCIPLINE	RESPONSIBILITY
	GEOLOGIST	TEAM LEADER
DRUCE MACK	1(SITE SAFETY OFFICE
		
WORK LIMITATIONS (TIME	e of day, etc.): DAY	CIGHT HOURS ONLY.
COMPENTS:		
		
·		